

Bacteria on surfaces in an apple cutting factory



Our RCI technology was needed to destroy several bacteria on the surfaces on the machines. Tests showed that there was a significant improvement after using the RCI technology. Far less bacteria etc. were found after the tests. These tests were done by the official food administration.